



01a




$EJ1=EJ0$, $EJ2=2\cdot EJ0$, $EJ0=10 \text{ MN}\cdot\text{m}\cdot\text{m}$
 $n1=2\cdot n0$, $n2=1\cdot n0$, $n0=500 \text{ kg}$
 $p=0,85\omega/1,05\omega_2$, $Fo=100 \text{ kN}$.

02a




$EJ1=EJ0$, $EJ2=2\cdot EJ0$, $EJ0=10 \text{ MN}\cdot\text{m}\cdot\text{m}$
 $n1=2\cdot n0$, $n2=1\cdot n0$, $n0=500 \text{ kg}$
 $p=0,8\omega/1,1\omega_2$, $Fo=100 \text{ kN}$.

05a




$EJ1=EJ0$, $EJ2=2\cdot EJ0$, $EJ0=10 \text{ MN}\cdot\text{m}\cdot\text{m}$
 $n1=3\cdot n0$, $n2=1\cdot n0$, $n0=500 \text{ kg}$
 $p=1,05\omega/1,05\omega_2$, $Fo=200 \text{ kN}$.

06a




$EJ1=EJ0$, $EJ2=2\cdot EJ0$, $EJ0=10 \text{ MN}\cdot\text{m}\cdot\text{m}$
 $n1=2\cdot n0$, $n2=1\cdot n0$, $n0=500 \text{ kg}$
 $p=0,85\omega/0,9\omega_2$, $Fo=150 \text{ kN}$.

09a




$EJ1=EJ0$, $EJ2=2\cdot EJ0$, $EJ0=10 \text{ MN}\cdot\text{m}\cdot\text{m}$
 $n1=3\cdot n0$, $n2=1\cdot n0$, $n0=500 \text{ kg}$
 $p=0,85\omega/1,05\omega_2$, $Fo=100 \text{ kN}$.

10a




$EJ1=EJ0$, $EJ2=2\cdot EJ0$, $EJ0=10 \text{ MN}\cdot\text{m}\cdot\text{m}$
 $n1=2\cdot n0$, $n2=1\cdot n0$, $n0=500 \text{ kg}$
 $p=0,8\omega/1,1\omega_2$, $Fo=100 \text{ kN}$.

13a



$EJ1=EJ0$, $EJ2=2\cdot EJ0$, $EJ0=10 \text{ MN}\cdot\text{m}\cdot\text{m}$
 $n1=3\cdot n0$, $n2=1\cdot n0$, $n0=500 \text{ kg}$
 $p=0,75\omega/1,05\omega_2$, $Fo=100 \text{ kN}$.

14a



$EJ1=EJ0$, $EJ2=2\cdot EJ0$, $EJ0=10 \text{ MN}\cdot\text{m}\cdot\text{m}$
 $n1=2\cdot n0$, $n2=3\cdot n0$, $n0=500 \text{ kg}$
 $p=1,1\omega/0,9 \omega_2$, $Fo=100 \text{ kN}$.